

BARRY GLASSMAN
HARFORD COUNTY EXECUTIVE

BILLY BONIFACE
DIRECTOR OF ADMINISTRATION



KAREN D. MYERS, CPPB
DIRECTOR OF PROCUREMENT

DEPARTMENT OF PROCUREMENT

**INVITATION FOR BIDS NO. 17-015
MT. SOMA BARN – WEATHERIZATION & STABILIZATION
ADDENDUM NO. 2**

October 3, 2016

Ladies and Gentlemen:

The purpose of this addendum is to provide clarification(s) to prospective bidders.

THE DUE DATE FOR THIS SOLICITATION HAS BEEN CHANGED FROM WEDNESDAY, OCTOBER 5, 2016 TO FRIDAY, OCTOBER 7, 2016; THE TIME DUE REMAINS THE SAME (1:00 P.M.).

QUESTION NO. 1: Is Barn to be totally repointed?

ANSWER NO. 1: See Addendum #1- question/answer #3.

QUESTION NO. 2: Are there special wage rates?

ANSWER NO. 2: There are no special wage rates with this project.

QUESTION NO. 3: There is no mention of a minimum minority percentage of participation. We assume this is not a requirement.

ANSWER NO. 3: There are no minority participation requirements with this project.

QUESTION NO. 4: Is there a specific bid bond form to be used?

ANSWER NO. 4: There is no standard form for the bid bond; your agent will create one with their format.

QUESTION NO. 5: What specifically is to be done with the metal panning around corn crib?

ANSWER NO. 5: See Addendum #1- question/answer #6.

QUESTION NO. 6: The drawings state the stone foundation wall is to be rebuilt prior to

MARYLAND'S NEW CENTER OF OPPORTUNITY

410.638.3550 | 410.879.2000 | TTY Maryland Relay 711 | www.harfordcountymd.gov

220 South Main Street, Bel Air, Maryland 21014

THIS DOCUMENT IS AVAILABLE IN ALTERNATIVE FORMAT UPON REQUEST

pouring the concrete buttresses at wall. We heard different at the pre-bid meeting.

ANSWER NO. 6: The stone foundation wall should be rebuilt prior to the pouring of the concrete buttress along the wall.

QUESTION NO. 7: What is the anticipated start date?

ANSWER NO. 7: November 1, 2016


QUESTION NO. 8: Can excavation spoils remain on site?

ANSWER NO. 8: Remove all spoils from the site.

QUESTION NO. 9: Note P under Project Description allows for planks or plywood where the floor is patched. Is this acceptable?

ANSWER NO. 9: Yes- this is acceptable. But if the Contractor uses plywood over the larger holes they need to include sub-framing so as not to exceed the span rating of the plywood.

Sincerely,



Stacy R. Rappold, CTPS
Procurement Agent III

SRR/vfy